

THE INSTRUCTION OF ELECTRIC DIGITAL INDICATOR 303-3499

Button Function:

1. Inch/mm Button ---inch/metric switching
2. ON/OFF Button --- ON/OFF the power
3. ZERO Button --- Setting zero

Usages Instruction:

1. Inch/mm Button ---inch/metric switching
 - Push inch/mm button, inch and metric measurement can be switched
2. ON/OFF Button --- ON/OFF the power
 - Push the button, it can be entered into measuring or close situation.
3. ZERO Button --- Setting zero
 - Push the button at any position, it can be displayed zero

Technical Parameter:

- Resolution: 0.00005in (0.001mm)
- Measuring Force: 1.5N
- Measuring Range: 0-0.5in (0-12.5mm)
- Max Speed: 2.36in/s (0.6m/s)
- Display: LCD